


FACE MASK FOR BEARD


SEWING METHOD :

STEP 1




- CUT 4 , JOIN RIGHT SIDES FACING AND STITCH CURVED SEAMS.

STEP 2




- JOIN FRONT TO BACK WITH RIGHT SIDES FACING IN AND STITCH THE TOP SEAM.
- TURN RIGHT SIDE OUT.

STEP 3



- HEM THE TOP OF THE POCKET THEN STITCH SIDES AND BOTTOM TO THE INSIDE OF THE MASK.

STEP 4



- FOLD IN AND HEM THE OUTER EDGE AND INSERT ELASTIC TO GATHER IN FROM LOWER EAR TO EAR
- STITCH EAR ELASTIC IN PLACE.